

Cherry Burton Sports Field Management Committee – Inspection Sunday 2 April 2017		
Present: T Baker, G Primarolo, P Wardale, A Addison		
Ref	Item	Action/Comment
1. Car Park and Access Road		
17/01/01	Access Road Surface	TB had arranged for some holes to be filled in. Complete
17/01/02	Car Park – Area in front of footpath	Area to be hatched with yellow paint to permit unrestricted access to footpath. M Lough has Completed.
17/01/03	Car Park – Emergency Access Point	Area in front of access point to be hatched with yellow paint. M Lough has volunteered, but loose surface unsuitable for white lining.
17/01/04	Fencing Repairs	LandPlan to install new fence. Now promised for Nov/Dec 2017.
2. Pavilion Exterior		
17/02/01	Baden Powell Section External Door	IK to paint it green to match as far as possible that of the other doors. IK to paint.
17/02/02	AED on W. wall.	Needs proximity light fitting. Agreed to go ahead Action P Wardale
3. Corridor		
	Spare Fluorescent Tubes	To be removed. Complete
4. Changing Room No. 1		
	AmbiRad heaters.	These are being turned on and left. Extra cost shown to be £3.50/day left on. Teams to be reminded that ambirads are for frost protection only in the winter – not for space heating during matches.
5. Changing Room No. 2		
	No comments	
6. Changing Room No. 3		
	No comments	
7. Equipment Room		
	No comments	
8. Lounge		
17/08/01	Tables blocking entrance to Lounge from Corridor	To be removed. Complete
17/08/02	Several squares of felt have been left against the wall.	To be removed. Complete
17/08/03	Safety alarm hanging next to lounge door.	To be removed. Complete
9. Kitchen		
17/09/01	Smoke Detector	Lid hanging open. Complete

17/09/02	Convactor Heater broken off wall	Not sure how this happened. To be refixed. IK to action
10. Toilets		
	No comments	
11. Baden Powell Section – Internals Not Inspected		
17/11/01	Roof Tiles	Broken tiles – need replacing. Complete
12. Perimeter		
17/12/01	Old Goalposts in NE corner of field	To be removed. Complete
17/12/02	Discarded wheelbarrow in copse S of field	To be removed. Complete
13. MUGA		
17/13/01	Bent Metal Cap near N. Goal post	Cap is a trip hazard and needs to be straightened out. Complete
14. Tennis Courts		
	No comments	
15. Former playground W. of field		
	No comments	
16. Outdoor Gym		
17/16/01	Bolt on step of walking machine is missing	New bolt to be fitted. Complete
17. Field		
17/17/01	Sight Screens	CBCC to look at means of securing the screens to improve stability during use. Sight recently blown down by wind. Near miss reported by pedestrian. To be moved to SW corner of field over winter. Screens should be laid flat after matches to ensure they can't get blown over. GP to comms to CBCC.
17/17/02	Old Storage Container S.W. Corner	CBCC to ensure removal now that ground is better for vehicular access. GP to ensure removal.
PJW		
8 Sept 2017		