| DATE OF WALKABOU | T: TIME: | SCHEDUL | E OF ISSUES | PARISH: | | | | | |
|---------------------------|---|--------------|-----------------|---------------------------|------------------|--|--|--|--|
| 12/5/2016 | 9:45am | OUTSIDE THE | REMIT OF THE | CHERRY BURTON | | | | | |
| MEETING PLACE: | | | | VILLAGE(S): | | | | | |
| Next to the pond, Main St | reet, Cherry Burton | VILLAGE TAS | KFORCE TEAM | Cherry Burton and Gardham | | | | | |
| PARISH AND AREA | Ruth Wilson (RW) | VTF | Ian Callan (IC) | HIGHWAYS AREA | Inin Sundan (IS) | | | | |
| LIAISON OFFICER: | Kutii Wiisoii (KW) | COORDINATOR: | ran Canan (IC) | ENGINEER: | Iain Sugdon (IS) | | | | |
| WALKABOUT | RW, IC and IS (ERYC) | | | | | | | | |
| ATTENDED BY: | TENDED BY: Cllr Peter Wardale, Cllr Nicola Jeffrey and Cllr James Slingsby (Parish Councillors) | | | | | | | | |

| ITEM NO. | VILLAGE/ROAD | ELEMENT | | | | LOCATION/DETAILS | COMMENTS |
|-------------|----------------|--|--|------------------------------|---|---|---|
| | CHERRY BURTON: | C'Way Pothole F'Way Pothole | | Signage Sweeping | | Pond – enquiry re: repair/repainting rails/posts. | - Private no ERYC responsibility |
| 1 | Main Street | Painting | | Other | | IS advised that this does not fall under ERYC's responsibility - the Parish Council will pursue with the appropriate people if necessary. | |
| 2 | Main Street | C'Way Pothole F'Way Painting | | Signage Sweeping Other | • | Outside no. 64 – ivy encroaching/overhanging footway. Referred to Paula Parker, Streetscene Enforcement Officer 24/05/16 to write to occupier. | |
| 3 | Main Street | C'Way Pothole F'Way Painting | | Signage Sweeping Other | | Outside 'Home Farm Cottage' – repair footway. Note made by IS - Highways Area Engineer - to arrange works (patching). | - Job to be issued for a 17 x 1.25m footway patch |
| 4 | Main Street | C'Way Pothole F'Way Pothole Painting | | Signage Sweeping Other | | Outside St Michael's Church/opposite 'Cherry Burton House' – fill pothole x 1. Note made by IS - Highways Area Engineer - to arrange works. | - Complete |
| 5 | Main Street | C'Way Pothole F'Way Pothole Painting | | Signage Sweeping Other | • | On wall of 'Hall Cottage' – enquiry re: two mirrors overhanging/obstructing the footway which were apparently installed by Mr Clark of Cherry Burton Hall – permission given? Note made by IS - Highways Area Engineer to investigate. | - Letter sent to property owner. Mirrors now removed. |

| ITEM NO. | VILLAGE/ROAD | ELEM | IENT | LOCATION/DETAILS | COMMENTS |
|-------------|--------------|--------------------------------------|------------------------|--|-------------------------------------|
| 6 | Main Street | C'Way F'Way Pothole Painting | Signage Sweeping Other | Next to pond/opposite Cherry Burton Play Area – reinstate offlet drain into pond. Note made by IS - Highways Area Engineer to arrange works. | - Job to be issued |
| 7 | Main Street | C'Way Pothole F'Way Pothole Painting | Signage Sweeping Other | The School Access Road' – entrance to Cherry Burton C Of E VC Primary School - enquiry made re: filling of potholes. \Photos\Cherry Burton 12-05-2016\001.JPG IS advised that as the area concerned is beyond the extent of the public highway - the school no doubt has its own arrangements in place regarding this type of work. | - Private road, not Adopted Highway |

| ITEM NO. | VILLAGE/ROAD | ELEM | MENT | LOCATION/DETAILS | COMMENTS |
|-------------|--------------|--|------------------------|--|----------------|
| | | C'Way Pothole | Signage | Outside no. 44 –hedge/vegetation | |
| 8 | Main Street | F'Way Pothole Painting | Other • | overhanging/obstructing the footway. 12/05/2016 10:14 | |
| 9 | Main Street | C'Way Pothole F'Way Pothole Painting | Signage Sweeping Other | Outside Costcutter/Post Office, 40 Main Street – damaged white verge markers (x 3 in no.). Note made by IS - Highways Area Engineer to arrange for replacements or wooden posts instead. | - Job complete |
| 10 | Main Street | C'Way Pothole F'Way Pothole Painting | Signage Sweeping Other | Repeat request by Parish Council (and a resident who approached us during the 'Walkabout') for a weight restriction through the village. Apparently been advised previously that the volume of vehicles does not meet the relevant criteria. Referred to Helen Firth, Senior Engineer - Traffic and Parking 24/5/16 for comment. | |

| ITEM NO. | VILLAGE/ROAD | ELE | ME | NT | | LOCATION/DETAILS | COMMENTS |
|-------------|--------------|--|----|------------------------------|---|--|---|
| 11 | Main Street | C'Way Pothole F'Way Pothole Painting | | Signage Sweeping Other | • | Between the Bay Horse Inn (no. 34) and Cherry Burton Village Hall (no. 4) – repair footway. Note made by IS - Highways Area Engineer - to arrange works ('top and turn'). | - Footway repairs to be undertaken in next financial year |
| 12 | Main Street | C'Way Pothole F'Way Pothole Painting | | Signage Sweeping Other | • | Outside no. 7 – request by Parish Council (JS) for hedge/vegetation to possibly be trimmed which is obstructing the footway. Referred to Paula Parker, Streetscene Enforcement Officer 24/05/16 to inspect and write to occupier if appropriate. | |
| 13 | Main Street | C'Way Pothole F'Way Painting | | Signage Sweeping Other | | Outside Cherry Burton Village Hall (no. 4) – replace pedestrian barriers (x 2 in no @ 4m.). Note made by IS - Highways Area Engineer. | - Job to be issued |
| 14 | Main Street | C'Way Pothole F'Way Pothole Painting | | Signage Sweeping Other | | Outside Cherry Burton Village Hall (no. 4) – clean out/repair gully. Note made by IS - Highways Area Engineer. | - Job complete, gully appears to be running ok |
| 15 | Main Street | C'Way Pothole F'Way Pothole Painting | | Signage Sweeping Other | • | Junction with Bishop Burton Road – enquiry made by Parish Council re; improving visibility at the junction. IS suggested possible build-out/extension of footway but budget constraints etc. | - Passed onto Asset Strategy for possible funding/scheme to be drawn up |

| ITEM NO. | VILLAGE/ROAD | ELE | ME | ENT | LOCATION/DETAILS | COMMENTS |
|-------------|--------------|--------------------------------------|----|------------------------------|--|--|
| 16 | Main Street | C'Way Pothole F'Way Pothole Painting | | Signage Sweeping Other | Crossroads - junction with the B1248 (Malton Road) and Leconfield Road – repeat request for improvements (traffic lights/roundabout) as concern re: speed of traffic/possible accidents here. Referred to Helen Firth, Senior Engineer - Traffic and Parking 24/5/16 for comment. | |
| 17 | Main Street | C'Way Pothole F'Way Painting | | Signage Sweeping Other | Next to bus shelter/Electric substation/opposite no. 10 – repair footway. Note made by IS - Highways Area Engineer (to 'top and turn'). | - Added to Slurry Sealing Programme |
| 18 | Canada Drive | C'Way Pothole F'Way Pothole Painting | | Signage Sweeping Other | Outside no. 3 Main Street/77 Canada Drive - hedge/vegetation obstructing/overhanging the footway. 12/05/2016 10:22 \Photos\Cherry Burton 12-05- 2016\003.JPG Referred to Paula Parker, Streetscene Enforcement Officer 24/05/16 to write to occupier. | |
| 19 | Canada Drive | C'Way Pothole F'Way Painting | • | Signage Sweeping Other | Outside nos. 73 and 75 – repair footway. Note made by IS - Highways Area Engineer (to 'top and turn' - will also offer a dropped kerb extension to no. 75). | - Added to Slurry Sealing Programme |

| ITEM NO. | VILLAGE/ROAD | ELE | ME | ENT | LOCATION/DETAILS | COMMENTS |
|-------------|------------------|--|----|------------------------------|--|--|
| 20 | Canada Drive | C'Way Pothole F'Way Painting | | Signage Sweeping Other | Outside no. 65, 67 and 150 – repair footway. Note made by IS - Highways Area Engineer (to repair and lift kerbs slightly). | Reset damaged kerbsFootway patching to be issuedArea added to Slurry SealingProgramme |
| 21 | Canada Drive | C'Way Pothole F'Way Painting | • | Signage Sweeping Other | Outside no. 61 – repair footway and kerb. Note made by IS - Highways Area Engineer (to repair footway and reset kerb). | - Job to be issued to replace kerb o/s 61 and o/s 144 |
| 22 | Canada Drive | C'Way Pothole F'Way Pothole Painting | | Signage Sweeping Other | Outside nos. 57/59 and 53/55 – repair footway. Note made by IS - Highways Area Engineer. | - Added to Slurry Sealing Programme |
| 23 | Elm Drive | C'Way Pothole F'Way Painting | • | Signage Sweeping Other | Outside no. 19 – repair footway/bury pipe (presumably installed by resident/to do with flooding some years ago?) Note made by IS - Highways Area Engineer. | - Job issued - Additional footway patch outside No 49 15m x 1.6m |
| 24 | Elm Canada Drive | C'Way Pothole F'Way Painting | | Signage Sweeping Other | On the corner/junction with nos. 20-44 (evens) – repair footway. Note made by IS - Highways Area Engineer – possible flood/erosion issue under footway (to refer to Yorkshire Water ['North Drain']). | Job to be issued 11m x 1.7m patch Passed onto Yorkshire Water to investigate |

| ITEM NO. | VILLAGE/ROAD | ELEMENT | | LOCATION/DETAILS | COMMENTS |
|-------------|--------------|--|-------------------------|---|------------------------------------|
| NO. | | C'Way Pothole F'Way Pothole Painting | Signage Sweeping Other | In corner of field – on the right hand side (when heading out of Cherry Burton)/on the south east side of the junction with the B1248 – tree leaning at an angle. | |
| 25 | Main Street | | | 12/05/2016 12:25\Photos\Cherry Burton 12-05- 2016\024.JPG | |
| | | | | Referred to Neil Lemmon, Arboriculture Supervisor 24/5/16 to inspect tree – is it a risk to highway users/do we need to write to the landowner? | |
| 26 | The Meadows | C'Way Pothole F'Way Painting | Signage Sweeping Other | Opposite no. 8 – repair footway. Note made by IS - Highways Area Engineer | - Job to be issues 7m x 1.8m patch |

| ITEM NO. | VILLAGE/ROAD | ELE | ME | NT | LOCATION/DETAILS | COMMENTS |
|-------------|--------------------|--|----|------------------------------|---|--|
| 27 | The Meadows | C'Way Pothole F'Way Pothole Painting | | Signage Sweeping Other | Outside no. 71 – repair footway. Note made by IS - Highways Area Engineer (patching). | - Job to be issues 7m x 1.8m patch + reset kerb |
| 28 | The Meadows | C'Way Pothole F'Way Painting | | Signage Sweeping Other | Outside no. 118 – repair surround to BT cover. IS to pass to Engineer/Assistant Engineer (to advise BT by way of a Section 81). | - Job issued |
| 29 | The Meadows | C'Way Pothole F'Way Pothole Painting | | Signage Sweeping Other | 'Playing Fields Access Road' – off The Meadows – enquiry made by Parish Council re: filling in a number of potholes here. IS advised that it is a private road and as such is not ERYC's responsibility - we are unable to help. | - Private no ERYC responsibility |
| 30 | The Meadows | C'Way Pothole F'Way Painting | | Signage Sweeping Other | Outside no. 126 – rocking BT cover. IS to pass to Engineer/Assistant Engineer (to advise BT by way of a Section 81). | - Section 81 issued to BT |
| 31 | Bishop Burton Road | C'Way Pothole F'Way Painting | • | Signage Sweeping Other | Outside no. 27/opposite no. 46 – concrete (inspection chamber?) lids (x 4 in total) are a trip hazard. Note made by IS - Highways Area Engineer (to refer to the appropriate ERYC officer/arrange as necessary). | - Added to Slurry Sealing Programme |
| 32 | Bishop Burton Road | C'Way Pothole F'Way Painting | | Signage Sweeping Other | Opposite no. 36 – same as item no. 31. Note made by IS - Highways Area Engineer (to refer to the appropriate ERYC officer/arrange as necessary). | - Added to Slurry Sealing Programme |
| 33 | Bishop Burton Road | C'Way Pothole F'Way Painting | | Signage Sweeping Other | Opposite no. 32/at junction with Two Riggs – KC cover – possible trip hazard. IS to pass to Engineer/Assistant Engineer (to advise BT by way of a Section 81). | - Section 81 issued to BT/KC |

| ITEM NO. | VILLAGE/ROAD | ELEMENT | | | LOCATION/DETAILS | COMMENTS |
|-------------|--------------------|--------------------------------------|------------------------------|--|--|-----------|
| 34 | Bishop Burton Road | C'Way Pothole F'Way Pothole Painting | Signage Sweeping Other | | At junction with Thornleys – damaged salt bin – the Parish Council advised that they did report this previously but nothing has happened. THORNLEYS 11 17 \Photos\Cherry Burton 12-05-2016\005.JPG Referred to Liam Jackson - Assistant Engineer 24/5/16 to inspect and comment. | |
| 35 | Highgate | C'Way Pothole F'Way Pothole Painting | Signage Sweeping Other | | Between end of footway (next to White Walls, no. 3 Highgate) and end of footway (next to junction of Highcroft), request for the bank to be pushed back (to reveal full extent/width of carriageway) and for the vegetation to be cut back — in view of narrowness of carriageway and poor visibility for drivers exiting Highcroft. General discussion re: how odd it is that the footway has a break in it here. | - Ongoing |

| ITEM NO. | VILLAGE/ROAD | ELEMENT | LOCATION/DETAILS | COMMENTS |
|-------------|--------------|---------|--|----------|
| NO. | VILLAGE/ROAD | ELEMENT | \Photos\Cherry Burton 12-05- 2016\006.JPG \Photos\Cherry Burton 12-05- 2016\007.JPG IS advised that this is no doubt because presumably this particular area of land is privately owned. Mapping system checked subsequently – historic maps show that there never used to be any footway here at all – one was presumably added when the houses in Highcroft were built? Don't | COMMENTS |
| | | | know if the landowner was approached (by us/developer?) at that time to ask | |

| ITEM NO. | VILLAGE/ROAD | ELEM | IENT | LOCATION/DETAILS | COMMENTS |
|-------------|--------------|--------------------------------------|------------------------------|--|---------------------|
| | | | | for part of his land to be changed to a footway? Can IS - Highways Area Engineer investigate and comment, and if appropriate, ask Streetscene Enforcement to contact landowner. In the meantime IC advised he would strim along the bottom of the bank - see item no. 17 on the other ('Village Taskforce') schedule. | |
| 36 | Highgate | C'Way Pothole F'Way Pothole Painting | Signage Sweeping Other | Outside no. 12 – request by Parish Council for area at back of footway to be cut/strimmed (a lot of dandelions, weeds and wild flowers here). Advised by IS and IC that not really appropriate as could lead to complaints from no. 12. Neighbours further along maintain a similar area outside their property. | - No further action |

| ITEM NO. | VILLAGE/ROAD | ELEMENT | | LOCATION/DETAILS | COMMENTS |
|-------------|------------------------|------------------------------|------------------------|--|--|
| | VILLAGE/ROAD Highgate | C'Way F'Way Pothole Painting | Signage Sweeping Other | LOCATION/DETAILS Outside no. 14 – standing water. 12/05/2016 11:22 \Photos\Cherry Burton 12-05- 2016\013.JPG | COMMENTS - To be ordered in the next financial year |
| | | | | \Photos\Cherry Burton 12-05- 2016\014.JPG IS - Highways Area Engineer to request Yorkshire Water to investigate. | |

| ITEM NO. | VILLAGE/ROAD | ELEM | IENT | LOCATION/DETAILS | COMMENTS |
|-------------|--------------|--------------------------------------|------------------------|--|----------|
| 38 | Highgate | C'Way Pothole F'Way Pothole Painting | Signage Sweeping Other | Outside no. 20 hedge/vegetation obstructing/overhanging the footway. .\Photos\Cherry Burton 12-05- 2016\008.JPG .\Photos\Cherry Burton 12-05- 2016\009.JPG Referred to Paula Parker, Streetscene Enforcement Officer 24/05/16 to write to occupier. | |

| ITEM NO. | VILLAGE/ROAD | ELEM | ENT | LOCATION/DETAILS | COMMENTS |
|-------------|------------------------|--------------------------------------|---------------------|--|----------|
| | VILLAGE/ROAD Highgate | C'Way Pothole F'Way Pothole Painting | Signage Sweeping | Outside 'Dale Garth' (no. 22) hedge/vegetation obstructing/overhanging the footway. \Photos\Cherry Burton 12-05- 2016\011.JPG \Photos\Cherry Burton 12-05- 2016\012.JPG Referred to Paula Parker, Streetscene | COMMENTS |
| | | | | Enforcement Officer 24/05/16 to inspect/write to occupier. | |

| ITEM NO. | VILLAGE/ROAD | ELEMENT | | | LOCATION/DETAILS COMMENTS | | |
|-------------|--------------|--------------------------------------|------------------------------|--|--|--|--|
| 40 | Highgate | C'Way Pothole F'Way Pothole Painting | Signage Sweeping Other | | Between the junctions of The Drive and Highcroft – refresh centre white lining as per existing – 4m mark, 2m gap (carriageway – 7m wide) – total distance of approx. 250m. IS to pass to Technical Assistant to order works. | - To be ordered in next financial year | |
| 41 | Highgate | C'Way Pothole F'Way Pothole Painting | Signage Sweeping Other | | At junction with Etton Road – fingerpost arms need repainting or possibly replacing. Concrete post needs repainting/possibly resetting too (leaning slightly). \Photos\Cherry Burton 12-05-2016\015.]PG BISHOP BURTON BISHOP BURTON ETTON 12/05/2016 12 15 | - Currently acceptable to be monitored | |

| ITEM NO. | VILLAGE/ROAD | ELEM | IENT | LOCATION/DETAILS | COMMENTS |
|-------------|--------------|---------------|----------|--|----------------------------------|
| | | | | BISHOP BURTON LECONFIELD BEVERLEY \Photos\Cherry Burton 12-05- 2016\018.JPG IS to pass to Jacqui Stipetic, Technical Assistant to inspect and comment. | |
| | | C'Way Pothole | Signage | Outside 'Old School House' (no. 1) – kerb | - To be issued in next financial |
| 42 | Highgate | F'Way Pothole | Sweeping | has dropped. | year |
| | | Painting | Other ■ | Note made by IS - Highways Area Engineer (to reset). | |

| ITEM NO. | VILLAGE/ROAD | ELEM | IENT | LOCATION/DETAILS | COMMENTS |
|-------------|--------------------|--------------------------------------|--------------------------------|---|--|
| 43 | Bishop Burton Road | Painting | Signage Sweeping Other Signage | On western side of junction with Highgate - kerb has dropped. Note made by IS - Highways Area Engineer (to reset - will also look at the possibility of installing proper dropped kerb crossing points at both sides of the junction). Where vehicles park at side of the road - on | - To be issued in next financial year - Added to Roadmaster |
| 44 | Etton Road | F'Way Pothole Painting | Sweeping Other | approach to bridge (over the old railway line) - heading from Cherry Burton towards Etton – deep drop at side of carriageway. Note made by IS - Highways Area Engineer (to investigate and comment). | Programme |
| 45 | Main Street | C'Way Pothole F'Way Pothole Painting | Signage Sweeping Other | In front of Cherry Burton Play Area – can the litterbin be repaired or replaced? IC (Village Taskforce) has advised he will repaint it in the meantime to cover up the damage /improve the look of it. \Photos\Cherry Burton 12-05-2016\016.JPG | |

| ITEM NO. | VILLAGE/ROAD | ELEMENT | | ENT | LOCATION/DETAILS | COMMENTS |
|-------------|--------------|------------------------------------|---|------------------------------|---|--|
| | | | | | Referred to Maureen Richardson, Operations Manager, Environmental Services 17/5/16 for inspection and comment re: possible repair/ replacement. Also included on other VTF schedule (item no. 21) for repainting in an effort to improve the look of the bin. | |
| 46 | Main Street | C'Way Pothole F'Way Painting | - | Signage Sweeping Other | Outside Costcutter/Post Office, 40 Main Street repair footway. Note made by IS - Highways Area Engineer (to 'top and turn') | - Added to Slurry Sealing Programme |
| 47 | Main Street | C'Way F'Way Pothole Painting | • | Signage Sweeping Other | Opposite Cherry Burton Play Area – repair arterial gully lid. Note made by IS - Highways Area Engineer (to repair/replace). | - To be issued |